





Northern Virginia Stream Restoration Bank Annual Status Report


December 15, 2011

Presented by Michael Rolband P.E., P.W.S., P.W.D., LEED® AP

Wetland Studies and Solutions, Inc.
5300 Wellington Branch Drive · Suite 100 · Gainesville · Virginia 20155
www.wetlandstudies.com



2011 Overall - NVSRB Progress



Snakeden Branch

- * 3.8 miles restored
- Lower reaches finishing 3rd growing season

The Glade

- * 3.8 miles restored
- Lower reaches finishing 2nd growing season


Colvin Run

- * 0.92 miles restored (4.1 miles to go!)
 - Forest Edge North July 2011
 - Forest Edge South April 2011
- Approval process in other reaches continue

Plus, endured catastrophic rain event!



NVSRB Colvin Run - Plan Approval Status





Catastrophic Storm Event: September 5-8, 2011


- 9.65 inches in 3 days with 5.4 inches falling in 3 hours
- Qualifies as 200-500 yr storm (per NOAA Atlas 14) for 3- & 6-hr storms

















The Glade – Reach 3 Channel Re-grade



• Deposition of material that washed out from upstream culvert system.








The Glade – Reach 4A 2-Step Cross Vane










- One rock slipped (only structure that had a problem).
- Placed rock behind vane arm.
- Re-graded and replanted area.

The Glade – Reach 6 Meander



- Design Plan Complete
- DRB Approved: 10/2011
- *Under Review with County and Agencies*






The Glade – Reach 6 (cont'd)

- Damage sustained in The Glade Reach 6
 - Approx. 200' of outside meander bend eroded (right bank)
 - Loss of vegetation on eroded bank
 - Reinforced bed deposited along right bank downstream of erosion
- Why the damage here?
 - Per citizen request, meander was not shifted toward the left bank, and the right bank was previously not protected by in-stream structures in an effort to protect:
 - Two (2) existing vernal pool wetland features (left bank), and
 - Mixed stand of primarily Eastern White Pine, Virginia Pine, and Red Maple trees (right bank)
 - No damage upstream or downstream of meander



The Glade – Reach 6 (cont'd)

- Proposed repairs (return to original design)
 - Install 2 new modified cross vanes
 - Install a 320' long, 12' wide bankfull bench with an imbricated rock wall on the right bank (allows vanes to work - increases flow conveyance capacity and reduces shear stress and velocity)
 - Repair small erosional area behind existing vane arm (at beginning of meander)
 - Tie-out grading to existing cross vane downstream of meander.
 - Plant heavily with native seed mix and tublings.














Wetland

fudies and Solutions, In

Colvin Run (Forest Edge North & South):


 Crews finished minor grading and redistribution.

September 12, 2

Final plantings scheduled for early next year.











Colvin Run (Forest Edge South):

• Filled abutments with concrete, re-graded and replanted.







