BEGIN RESTORATION AT CULVERT UNDER BARON CAMERON AVENUE

BARON CAMERON AVENUE

2003 COUNTY MAPPED RPA

STREAM RESTORATION EASEMENTS D.B. 19148, P.G. 124 D.B. 19148, P.G. 158

TEMPORARY EASEMENT D.B. 21137, P.G. 913

BUTTERMILK CREEK

TRANSCONTINENTAL GAS PIPELINE CORPORATION RIGHT OF WAY AND ESMT (DB 795, PG 541 AND DB 2163, PG 338)

10804 HUNT CLUB ROAD

EX. 10' SAN SEW ESMT (DB 3511, PG 267)

TRIBUTARY 1

EX. 20' SAN SEW ESMT (DB 3097, PG 316)

STREAM RESTORATION EASEMENTS D.B. 19148, P.G. 124 D.B. 19148, P.G. 158

TRIBUTARY 2

EX. 10' SAN SEW ESMT

EX. 15' SAN SEW ESMT

1319 WESTHILLS LANE

TEMPORARY ACCESS PATH

1323 BUTTERMILK LANE

WESTHILLS LANE

BUTTERMILK LANE

HUNT CLUB ROAD

10820 HUNT CLUB ROAD

1333 BUTTERMILK LANE

TRIBUTARY 3

EX. 15' STM SEW ESMT

RING ROAD

CONSTRUCTION ACCESS SHALL BE FROM RING ROAD

END RESTORATION AT CULVERT UNDER HUNT CLUB ROAD

HARRON

GRAPHIC SCALE

50 0 25 50 100 200

(IN FEET) 1 inch = 50 feet

Wetland Studies and Solutions, Inc.

5300 Wellington Branch Drive, Suite 100 • Gainesville, VA 20155

Phone 703 679 5600 • Fax 703 679 5601

wetlandstudies.com

Northern Virginia Stream Restoration Bank
Colvin Run - Buttermilk Creek

Fairfax County, Virginia

Overall Site Exhibit

Copyright © 2012 Wetland Studies and Solutions, Inc.

COMMONWEALTH OF VIRGINIA PROFESSIONAL ENGINEER FRANK R. GRAZIANO Lic. No. 032099

REVISIONS				
No.	Date	Description	Rev. By:	App. By:

SCALE: 1" = 50'

DATE: SEPTEMBER 2012

Horizontal Datum: VCS NAD 83

Vertical Datum: NGVD 29

Boundary and Topo Source: WSSI and Fairfax Digital Data

Design	Draft	Approved
SRP	SRP	FRG

Sheet # 2 of 54

Computer File Name: L:\2000\04\200\6.0\CADD\64ENGR\10-Planset OVERALL SITE EXHIBIT 01.dwg