


SEE SHEET 5 FOR GRADING AND LONGITUDINAL PROFILE LEGENDS AND NOTES.




- GENERAL NOTES:**
- LIMITED TO WITHIN THE EXISTING CHANNEL, AS MUCH AS POSSIBLE USING SUITABLE TRACKED EQUIPMENT TO LIMIT IMPACT TO TREES AND OTHERWISE STABLE BANKS.
  - CONTACT MISS UTILITY (800-552-7001) PRIOR TO COMMENCING ANY WORK.
  - PRIOR TO CONSTRUCTION, LOC SHALL BE WALKED WITH WSSI STAFF TO CONFIRM TREE REMOVAL.
- CONSTRUCTION ACCESS NOTES:**
- ACCESS TO STAGING AREAS FROM NORTH SHORE DRIVE VIA SUNDER COURT.
  - PARALLEL PARKING WITHIN LIMITS OF CLEARING SHALL BE RESTRICTED DURING CONSTRUCTION HOURS. CONES SHALL BE USED TO BLOCK PARKING SPACES AND SIGNS SHALL BE POSTED WITH RESTRICTED HOURS.
  - A FLAGPERSON WILL BE ON SITE TO ASSIST WITH TRAFFIC DURING DELIVERIES. HOA CONTACT PERSON SHALL BE NOTIFIED IF ANY DELIVERIES WILL BLOCK ACCESS FOR AN EXCESSIVE PERIOD. DELIVERIES SHALL BE COORDINATED WITH THE CONSTRUCTION MANAGER WILL DISCUSS DELIVERY TIMES WITH THIS CONTACT PERSON.

LONGITUDINAL PROFILE SCALE: H: 1" = 20' V: 1" = 2'

REVISIONS		Rev. By	App. By
No.	Date	Description	

DATE: OCTOBER 2011 SCALE: 1" = 20'



Northern Virginia Stream Restoration Bank  
 Lake Anne West  
 Fairfax County, Virginia

Grading Plan and Longitudinal Profile

Copyright © 2011 Wetland Studies and Solutions, Inc.

**Wetland**  
 Studies and Solutions, Inc.

5300 Wellington Branch Drive, Suite 100 • Gainesville, VA 20155  
 Phone 703 679 5600 • Fax 703 679 5601  
 wetlandstudies.com