



THIS SHEET TO BE USED FOR TREE REMOVAL PURPOSES ONLY.

IT IS ASSUMED THAT ALL TREES WITHIN THE LIMITS OF CLEARING WILL NOT BE REMOVED. PRIOR TO CONSTRUCTION, THE LIMITS OF CLEARING (LOC) SHALL BE WALKED BY WSSI STAFF TO CONFIRM TREE REMOVAL. IN THE EVENT THAT THE CONTRACTOR BELIEVES A TREE WITHIN THE LOC COULD BE SAVED, THE CONTRACTOR SHALL CONTACT WETLAND STUDIES AND SOLUTIONS, INC. AND HAVE THE PROJECT ENGINEER DETERMINE IF THE TREE SHOULD BE SAVED OR REMOVED.

TREE REMOVAL LEGEND	
	PROPERTY BOUNDARY
	COMBINED STREAM ESMNT AND TEMP GRADING & CONST. / INGRESS-EGRESS ESMNT
	STREAM ESMNT
	TEMP GRADING & CONSTRUCTION ESMNT / INGRESS-EGRESS ESMNT
	EXISTING EASEMENTS
	EXISTING INFRASTRUCTURE
	EXISTING SANITARY SEWER
	EXISTING CONTOURS (0.5')
	PROPOSED CONTOURS
	PROPOSED STREAM CENTERLINE
	PROPOSED TOP OF BANK
	NONPERENNIAL STREAM (EXISTING TOP OF BANK)
	PERENNIAL STREAM (EXISTING TOP OF BANK)
	JURISDICTIONAL WETLANDS
	LTS - LIMITS OF TREE SURVEY
	LOC-TP - LIMITS OF CLEARING/TREE PROTECTION
	SSF - SUPER SILT FENCE
	TREE TO BE REMOVED
	TREE ALREADY PROPOSED FOR REMOVAL AS PART OF THE NEARBY RESTORATION (PROVIDED UNDER SEPARATE COVER)

REVISIONS				
No.	Date	Description	Rev. By	App. By

Horizontal Datum: VCS NAD 83
 Vertical Datum: NGVD 29
 Boundary and Topo Source: WSSI and Fairfax Digital Data

Design	Draft	Approved
KLP	KLP	FRG

Sheet # 26 of 69
 Computer File Name: TREE REMOVAL PLAN.DWG



Northern Virginia Stream Restoration Bank
 Colvin Run - Wiehle South
 Fairfax County, Virginia

Tree Removal Plan

Copyright © 2012 Wetland Studies and Solutions, Inc.

5300 Wellington Branch Drive, Suite 100 • Gainesville, VA 20155
 Phone 703 679 5600 • Fax 703 679 5601
 wetlandstudies.com