


MATCHLINE A - SEE SHEET 1

MATCHLINE B - SEE SHEET 3



REACH 5 LEGEND	
--- PROPERTY BOUNDARY & STREAM ESMNT, TEMP. GRADING & CONST. ESMNT, & INGRESS-EGRESS ESMNT	▲ NEST
--- STREAM ESMNT, TEMP. GRADING & CONST. ESMNT, & INGRESS-EGRESS ESMNT	■ CAVITY
--- EXISTING CONTOURS (0.5)	○ SUBSURFACE EROSIONAL FEATURE
--- EXISTING INFRASTRUCTURE	◇ SNAG
--- FLOODPLAIN EASEMENT	◆ DEN
--- NONPERENNIAL STREAM (EXISTING TOP OF BANK)	○ TREE DRIPLINE
--- PERENNIAL STREAM (EXISTING TOP OF BANK)	
--- JURISDICTIONAL WETLAND AREAS	
--- LTS - LIMITS OF TREE SURVEY	

NORTHERN VIRGINIA STREAM RESTORATION BANK
THE GLADE - REACH 5
 Fairfax County, Virginia

EXISTING CONDITIONS

Copyright © 2009 Wetland Studies and Solutions, Inc.

REVISIONS						H. D.: VCS NAD 83 V. D.: NGVD 29		
No.	Date	Description	Rev. By	App. By		Rev. By	App. By	Boundary and Top Source: WSSI and Fairfax Digital Data
								Design
								Draft
								Approved
								MFA
								MFA
								FRG
								Sheet #
								2 of 4

DATE: APRIL 17, 2009 SCALE: 1" = 30' C.I. = 0.5'

Wetland
 Studies and Solutions, Inc.[®]

5300 Wellington Branch Drive, Suite 100 • Gainesville, VA 20155
 Phone 703 679 5600 • Fax 703 679 5601
 wetlandstudies.com

Computer File Name:
 L:\2009\04\17\20090417_01.dwg