



REACH 5 LEGEND

--- PROPERTY BOUNDARY & STREAM ESMNT, TEMP. GRADING & CONST. ESMNT, & INGRESS-EGRESS ESMNT	▲ NEST
--- STREAM ESMNT, TEMP. GRADING & CONST. ESMNT, & INGRESS-EGRESS ESMNT	■ CAVITY
--- EXISTING CONTOURS (0.5')	○ SUBSURFACE EROSIONAL FEATURE
--- EXISTING INFRASTRUCTURE	◆ SNAG
--- FLOODPLAIN EASEMENT	⊕ DEN
--- NONPERENNIAL STREAM (EXISTING TOP OF BANK)	⋈ TREE DRIPLINE
--- PERENNIAL STREAM (EXISTING TOP OF BANK)	
--- JURISDICTION WETLAND AREAS	
--- LTS --- LIMITS OF TREE SURVEY	

NORTHERN VIRGINIA STREAM RESTORATION BANK
THE GLADE - REACH 5
 Fairfax County, Virginia

EXISTING CONDITIONS

Copyright © 2009 Wetland Studies and Solutions, Inc.

REVISIONS

No.	Date	Description	Rev. By	App. By	No.	Date	Description	Rev. By	App. By

Wetland
 Studies and Solutions, Inc.
 5300 Wellington Branch Drive, Suite 100 • Gainesville, VA 20155
 Phone 703 679 5600 • Fax 703 679 5601
 wetlandstudies.com