




MATCHLINE C SEE SHEET 3



REACH 5 LEGEND	
---	PROPERTY BOUNDARY & STREAM ESMNT, TEMP. GRADING & CONST. ESMNT, & INGRESS-EGRESS ESMNT
---	STREAM ESMNT, TEMP. GRADING & CONST. ESMNT, & INGRESS-EGRESS ESMNT
---	EXISTING CONTOURS (0.5')
---	EXISTING INFRASTRUCTURE
---	FLOODPLAIN EASEMENT
---	NONPERENNIAL STREAM (EXISTING TOP OF BANK)
---	PERENNIAL STREAM (EXISTING TOP OF BANK)
---	JURISDICTIONAL WETLAND AREAS
---	LTS - LIMITS OF TREE SURVEY
▲	NEST
■	CAVITY
○	SUBSURFACE EROSIONAL FEATURE
◇	SNAG
+	DEN
○	TREE DRIPLINE

NORTHERN VIRGINIA STREAM RESTORATION BANK
THE GLADE - REACH 5
 Fairfax County, Virginia

EXISTING CONDITIONS

Copyright © 2009 Wetland Studies and Solutions, Inc.

REVISIONS							
No.	Date	Description	Rev. By	App. By	No.	Date	Description

Wetland
 Studies and Solutions, Inc.[®]

5300 Wellington Branch Drive, Suite 100 • Gainesville, VA 20155
 Phone 703 679 5600 • Fax 703 679 5601
 wetlandstudies.com

DATE: APRIL 17, 2009 SCALE: 1" = 30' C.I. = 0.5'

H. D.: VCS NAD 83 V. D.: NGVD 29		
Boundary and Topo Source: WSSI and Fairfax Digital Data		
Design	Draft	Approved
MFA	MFA	FRG
Sheet #		
4 of 4		
Computer File Name:		