

**Northern Virginia Stream Restoration Bank
Snakeden Stream Restoration Construction Photos**



Figure 1. Reach 6A – After construction and planting



Figure 2. Reach 6B – During Construction



Figure 3. Reach 6B –Planting after construction



Figure 4. Reach 8 – During Construction



Figure 5. Reach 8A – Construction with minimal disturbance



Figure 6. Reach 8A – Corridor with minimal disturbance



Figure 7. Reach 10 –after construction